

Via Maltese, 62/64 - 90146 Palermo (PA) - Italia
 Tel. 091 685 1784 Mobile +39 351 8753628
 e-mail: info@allfoodproject.com website: www.allfoodproject.com.com
 C.F. GLLBGI66L21G273C VAT Number 03765550821 Company Registered Number 162241

Estimate No. **6929** of the **01/02/2026**

Info

CALL us for FREE consulting service Tel 091 685 1784 or CHAT with us on Whatsapp +393518753628

Cod. art.	Description	Qty	Price	Discount	Amount
-----------	-------------	-----	-------	----------	--------

AFP/FAST6
L1100

FAST6 ice-cream wells bench without reserve

1

€6,316.00



- Ventilated model - Power supply v 230 / 50hz single-phase
 - N. 6 wells, built-in condensing unit -
 Measurements cm l 110
 xp 70 xh 100,2

Optional :

- Carapina with 3.5 Lt anti-rotation system
- Glass door number 4 wells
- Number 6 stainless steel carapins with anti-rotation system -
- Capacity 7 lt
- Room glass door for number 2 wells
- scoopwash

Technical Sheet

Customizable model on the sides and front	Electronic control panel with digital display
Carapine not included	V 230 / 50Hz single-phase power supply
Ventilated system	Power 621 W
Base in galvanized sheet covered with a base in similinox sheet	Operating temperature C -2 / -18
Upper structure in white prepainted sheet	Yield 472 W / -30 C
Stainless steel top with Scotch Brite finish	Tested at 30 C and 55% RH
Removable rear ventilation grille for access to the engine compartment	Total dimensions cm W 110 x D 70 xh 100.2
4 wheels facilitate the movement of the bench	Manual defrosting
Bath n. 6 wells ventilated ice cream Panorama without reserve	CE standard
Exclusive anti-rotation system of carapine (not included)	On-board condensing unit



[+ Add Product](#)



For countries outside of Italy, shipping costs may vary. We will send you a quotation after receiving this order confirmation.

Pursuant to Legislative Decree 196/2003 we only use your data for the purpose of communicating with existing commercial relations between us.
Please check your personal data, VAT number and Tax Code. We are not responsible for any errors.